



ISO/IES 17025:2006 (cert. № 4K051)



Quality management system ISO 9001:2015 (cert. № U228396)



MICROTECH

 \sum



1.MODIFICATIONS

ltem No	Range	Resolution	Accuracy*	Jaw lenth	Optimal measuring force	Proof	Data output
	mm	mm	mm	mm	N		
141099192	0-150	0,001	±0,005	40	8	IP-67	RS-232
141099293	0-199.9	0.001	±0.007	50	8	IP-67	RS-232

*MAX ERROR FOR INTERNAL END DEPTH MEASUREMENTS DIN-862

2.BUTTON FUNCTIONS





3.0PERATION INSTRUCTIONS

3.1 Wipe with a clean cloth, soaked in gasoline, measuring surface of the frame and gauge calipers to remove anti-corrosion oil. Then wipe them with a clean dry cloth.

3.2 If necessary, open the battery cover; insert the battery (type CR2032) according to the polarity of the electrodes. Blinking display information or absence suggests replacing battery.

3.3 Check the zero setting of the caliper. Sum the measuring jaws to contact with each other. Force is generated with a measuring force indication. To create the recommended force (8N) by the block adjustment and press SET button.

3.4 During the measurement, measuring jaws should to sum to the measured object without knocking.

3.5 During the measurement avoid warps of measuring surfaces of the instrument. Measuring surface must be fully in contact with the measurement object.

3.6 Optimal measuring force for this size caliper 8±2N. During a measuring process control optimal measuring force on Measuring force indication window

3.7 After finishing work wipe the measuring surfaces of the caliper with a cloth soaked in gasoline and apply anticorrosion oil.




WARNING!

IN THE PROCESS OF WORKING WITH CALIPERS SHOULD BE AVOIDED: Scratches on the measuring surfaces: Measuring the size of object in the process of machining; Shocks or dropping, avoid bending of rod or other surfaces.

ISO 17025 ISO 9001:2015



4.INSTRUMENT FIGURE



Change without prior notice

ISO 17025 ISO 9001:2015 made in Ukraine 🛤

Edition: M1019 0818